

FwE Attached :: MW010and MW020schematics

David Jewett to: Steven Acree, Dominic Digiulio, Randall Ross,

Rick Wilkin

12/19/2012 02:58 PM

Trash the previous schematic for MW02. This is the correct version!

- dgj -

David G. Jewett, Ph.D. Chief, Subsurface Remediation Branch

U.S. Environmental Protection Agency
Office of Research and Development
National Risk Management Research Laboratory
Ground Water and Ecosystems Restoration Division
Mail: P.O. Box 1198, Ada, Oklahoma 74821

Phone: 580.436.8560 E-mail: jewett.david@epa.gov

---- Forwarded by David Jewett/ADA/USEPA/US on 12/19/2012 02:57 PM -----

From: Kathy Tynsky/ADA/USEPA/US
To: Randall Ross/ADA/USEPA/US@EPA
Cc: David Jewett/ADA/USEPA/US@EPA

Date: 12/19/2012 02:14 PM

Subject: Re: Fw: Attached: MW01 and MW02 schematics

Is fixed! Sank U!!



Fig 6b - Completion log MW02.tif

Randall Ross The arrow describing the pump on the right side... 12/19/2012 02:08:25 PM

From: Randall Ross/ADA/USEPA/US
To: David Jewett/ADA/USEPA/US@EPA
Cc: Kathy Tynsky/ADA/USEPA/US@EPA

Date: 12/19/2012 02:08 PM

Subject: Re: Fw: Attached: MW01 and MW02 schematics

The arrow describing the pump on the right side of well needs to be moved up so it points to the pump instead of to the top part of the screen.

r^3

.....

Randall R. Ross, PhD
U.S. Environmental Protection Agency
National Risk Management Research Laboratory
Ground Water and Ecosystems Restoration Division
Applied Research and Technical Support Branch
P.O. Box 1198 / 919 Kerr Research Dr.

Ada, OK 74820

580-436-8611 voice / 580-436-8614 fax

Email: ross.randall@epa.gov
